



Part.no	Model	Cena netto 2023 €
<b>PIONER 8 Mini, incl. oars</b>		<b>1 828 €</b>
<b>PIONER 10 Classic</b>		<b>2 945 €</b>
4510071	Steering console low, w/cable,	947 €
4510070	Steering console high, w/cable, space for 5' plotter	971 €
8510090	Handrails front,	582 €
8510091	Handrails back	210 €
8510094	A-frame w/center lantern light,	844 €
4510095	Cushions, set of 3 pc.,	549 €
4514070	Safety ladder,	165 €
8545096	Lantern incl cables	181 €
4510050	Rear seat box (only in comb. with steering console)	493 €
4450008	Oars	106 €
4551510	Mouning plate for sonar	228 €
<b>PIONER 11 Easy, incl. oars NEW!</b>		<b>3 183 €</b>
4514070	Safety ladder	165 €
8801062	Cover strips for deck (set)	242 €
<b>PIONER 12 Maxi w/rear seat box</b>		<b>3 721 €</b>
4510070	Steering console high, w/cable, space for 5' plotter, <b>SE/AE</b>	971 €
4510071	Steering console low, w/cable	947 €
8510090	Handrails front	582 €
8510091	Handrails back	210 €
8510094	A-frame w/center lantern light,	844 €
4512097	Cushions, set of 3 pc.,	678 €
4514070	Safety ladder,	165 €
8545096	Lantern incl cables	181 €
4450009	Oars	109 €
4551510	Mouning plate for sonar	228 €
<b>PIONER 13, incl. oars</b>		<b>3 739 €</b>
4513090	Handrails front	484 €
4515091	Handrails back	360 €
8513095	Cushions, set of 3 pc.	587 €
<b>PIONER 14 Active</b>		<b>5 250 €</b>
4514195	Black console, w/cable,	1 076 €
4514080	Windscreen,	206 €
4514079	Windscreen rail,	543 €
4514090	Handrails front,	690 €
4515091	Handrails back,	360 €
4514098	Backsupport w/cushion,	755 €
4514099	A-frame w/lantern lights, incl. Backsupport, <b>AE</b>	1 591 €
4545096	Lantern incl switch and cables	423 €
8514095	Cushions, set of 3 pc.,	838 €
4514070	Safety ladder,	165 €
8514395	Cover for console	336 €
4551510	Mouning plate for sonar	228 €
4450009	Oars	109 €
4514100	FISHER: Fishing deck, fixing plate for elcetric front engine	3 247 €
4514198	FISHER: Black console "low" w/cable, Fisher	1 075 €
4514091	FISHER: Handrails front	656 €
8551095	FISHER: Cushion for backbench	388 €
8551096	Fixing plate el.front engine, Included in part. no. 4514100	483 €

**NEXT PAGE, MORE ABOUT PIONER 14 FISHER!**

<b>PIONER 14 Fisher (P14 Active + part. no. 4514100)</b>		<b>8 497 €</b>
4514195	Black console w/cable,	<b>1 076 €</b>
4514080	Windscreen ,	<b>206 €</b>
4514079	Windscreen rail,	<b>589 €</b>
4514198	Black console "low" w/cable, Fisher	<b>1 075 €</b>
4514091	Handrails front,	<b>656 €</b>
4515091	Handrails back,	<b>360 €</b>
4514098	Backsupport w/cushion	<b>755 €</b>
4514099	A-frame w/lantern lights, incl. backsupport	<b>1 591 €</b>
4545096	Lantern incl switch and cables	<b>423 €</b>
8551095	Cushion for backbench	<b>388 €</b>
4514070	Safety ladder,	<b>165 €</b>
4551510	Mouning plate for sonar,	<b>228 €</b>

<b>PIONER 15 Allround</b>		<b>6 558 €</b>
4515594	Black console w/cable,	<b>1 101 €</b>
4515580	Windscreen,	<b>342 €</b>
4515579	Windscreen rail,	<b>563 €</b>
4515590	Handrails front,	<b>710 €</b>
4515591	Handrails back,	<b>275 €</b>
4515596	A-frame w/lantern lights,	<b>1 268 €</b>
4515597	Backsupport w/cushion,	<b>629 €</b>
4545094	Lantern incl switch and cables	<b>423 €</b>
8515595	Cushions, set of 3 pc.,	<b>948 €</b>
4515506	Safety ladder,	<b>524 €</b>
8515495	Cover for console	<b>399 €</b>
4551510	Mouning plate for sonar	<b>228 €</b>
4450009	Oars	<b>109 €</b>

<b>PIONER 16 Explorer</b>		<b>9 372 €</b>
<b>4416949</b>	<b>PIONER 16 Explorer<sup>+</sup> SE "Narrow"</b>	<b>13 861 €</b>
4416595	Narrow console w/hydraulic steering <sup>1</sup> , <b>SE Narrow</b>	
4515580	Windscreen for narrow console, <b>SE Narrow</b>	
4515579	Windscreen rail for narrow console, <b>SE Narrow</b>	
4416090	Handrails front, <b>SE Narrow</b>	
4416096	Backsupport with cushion, <b>SE Narrow</b>	
4416191	Extra seatbox, narrow, <b>SE Narrow</b>	
8652070	Safety ladder, telescopic, <b>SE Narrow</b>	
<b>4416849</b>	<b>PIONER 16 Explorer<sup>+</sup> AE "Double"</b>	<b>17 880 €</b>
4416595	Narrow console w/hydraulic steering <sup>1</sup> , <b>AE Double</b>	
4416195	Console for passenger, <b>AE Double</b>	
4515580	Windscreen for narrow console, <b>AE Double, 2 pc.</b>	
4515579	Windscreen rail for narrow console, <b>AE Double, 2 pc.</b>	
4416090	Handrails front, <b>AE Double</b>	
4416094	A-frame with lantern lights, <b>AE Double</b>	
4416096	Backsupport with cushion, <b>AE Double</b>	
8416095	Cushions front and stern, set of 2 pc. <b>AD Double</b>	
4416191	Extra seatbox, narrow, <b>AE Double, 2pc.</b>	
8416097	Cuchion for extra seatbox narrow, <b>AE Double, 2 pc.</b>	
8652070	Safety ladder, telescopic, <b>AE Double</b>	
<b>4416959</b>	<b>PIONER 16 Explorer<sup>+</sup> SE "Wide"</b>	<b>14 322 €</b>
4416196	Wide console with hydraulic steering <sup>1</sup> , <b>SE Wide</b>	
4416080	Windscreen for wide console, <b>SE Wide</b>	
4416079	Windscreen rail for wide console, <b>SE Wide</b>	
4416090	Handrails front, <b>SE Wide</b>	
4416096	Backsupport with cushion, <b>SE Wide</b>	
4416192	Extra seatbox, wide, <b>SE Wide</b>	
8652070	Safety ladder, telescopic, <b>SE Wide</b>	
<b>4416859</b>	<b>PIONER 16 Explorer<sup>+</sup> AE "Wide"</b>	<b>16 399 €</b>
4416196	Wide console with hydraulic steering <sup>1</sup> , <b>AE Wide</b>	
4416080	Windscreen for wide console, <b>AE Wide</b>	
4416079	Windscreen rail for wide console, <b>AE Wide</b>	
4416090	Handrails front, <b>AE Wide</b>	
4416094	A-frame with lantern lights, <b>AE Wide</b>	
4416096	Backsupport with cushion, <b>AE Wide</b>	
8416095	Cushions front and stern, set of 2 pc. <b>AE Wide</b>	
4416192	Extra seatbox, wide, <b>AE Wide</b>	
8416098	Cuchion for extra seatbox wide, <b>AE Wide</b>	
8652070	Safety ladder, telescopic, <b>AE Wide</b>	

<b>PIONER 16 Explorer: Extra equipmnet</b>		
4416595	Narrow console w/hydraulic steering <sup>1</sup> , <b>SE Narrow /AE Do</b>	<b>2 259 €</b>
4416195	Console for passenger, <b>AE Double</b>	<b>1 009 €</b>

4515580	Windscreen for narrow console, <b>SE Narrow/2pc. AE Dou</b>	<b>342 €</b>
4515579	Windscreen rail for narrow console, <b>SE Narrow/ 2pc. AE I</b>	<b>563 €</b>
4416196	Wide console with hydraulic steering <sup>1</sup> , <b>SE Wide/AE Wide</b>	<b>2 657 €</b>
4416080	Windscreen for wide console, <b>SE Wide/AE Wide</b>	<b>386 €</b>
4416079	Windscreen rail for wide console, <b>SE Wide/AE Wide</b>	<b>610 €</b>
4416090	Handrails front, <b>SE/ AE</b>	<b>773 €</b>
4416094	A-frame with lantern lights, <b>AE</b>	<b>1 647 €</b>
4545094	Lantern incl switch and cables	<b>423 €</b>
4416096	Backsupport with cushion, <b>SE/ AE</b>	<b>999 €</b>
8416095	Cushions front and stern, set of 2 pc. <b>AE</b>	<b>648 €</b>
4416191	Extra seatbox, narrow, <b>SE/ 2pc. AE Double</b>	<b>425 €</b>
8416097	Cuchion for extra seatbox narrow, <b>2pc. AE Double</b>	<b>269 €</b>
4416192	Extra seatbox, wide, <b>SE/ AE</b>	<b>493 €</b>
8416098	Cuchion for extra seatbox wide, <b>AE</b>	<b>337 €</b>
8652070	Safety ladder, telescopic, <b>SE/ AE</b>	<b>313 €</b>
8515495	Cover for narrow console	<b>399 €</b>
8416496	Cover for wide console	<b>404 €</b>
4551510	Mouning plate for sonar	<b>228 €</b>

### PIONER Multi III

14 946 €

8800992	<b>S.t.b. discontinued</b> Wide console <b>SB</b> w/hydraulic steerin	<b>2 673 €</b>
4416196	<b>NEW</b> Wide <b>center</b> console w/hydraulic steering <sup>1</sup>	<b>2 657 €</b>
4550296	Narrow console w/hydraulic steering <sup>1</sup>	<b>2 259 €</b>
4550194	Console for passenger	<b>903 €</b>
8517079	<b>S.t.b. discontinued</b> Windscreen rail for wide console <b>SB</b>	<b>911 €</b>
4416079	<b>NEW</b> Windscreen rail for wide <b>center</b> console	<b>610 €</b>
4514079	Windscreen rail for narrow console	<b>543 €</b>
8652080	<b>S.t.b. discontinued</b> Windscreen for wide console <b>SB</b>	<b>327 €</b>
4416080	<b>NEW</b> Windscreen for wide <b>center</b> console	<b>386 €</b>
4514080	Windscreen for narrow console	<b>206 €</b>
4550094	A-frame w/lantern lights, 2pc x fishing rod holders	<b>1 572 €</b>
4550096	Backsupport w/cushion (for mount on A-frame)	<b>654 €</b>
4545094	Lantern incl switch and cables	<b>423 €</b>
4515091	Handrails, 1 pair	<b>360 €</b>
8550093	Stainless steel boarding bow rail	<b>480 €</b>
4550082	Cover f. stern, textile, only in comb. with 2x narrow consol	<b>2 063 €</b>
4551639	Extra seatbox	<b>493 €</b>
4416192	Extra seatbox wide, <b>center</b>	<b>337 €</b>
8517099	Cuchion for extra seatbox	<b>440 €</b>
8416098	Cuchion for extra seatbox wide, <b>center</b>	<b>317 €</b>
8517395	Cover for wide console <b>SB</b>	<b>381 €</b>
8416496	Cover for wide <b>center</b> console	<b>404 €</b>
8514395	Cover for narrow or passenger console	<b>336 €</b>
8551095	Cushion for backbench	<b>388 €</b>
4514070	Safety ladder	<b>165 €</b>
4551510	Mouning plate for sonar	<b>228 €</b>

### PIONER 17 Flexi, w/hyd. s.<sup>1</sup>

14 305 €

8517079	Windscreen rail,	<b>911 €</b>
4517192	A-frame w/lantern lights,	<b>1 586 €</b>
4517094	Backsupport w/cushion,	<b>891 €</b>
8517395	Cover for console	<b>382 €</b>
8517095	Cushions for backbench, set of 2 pc.	<b>495 €</b>
8517097	Cushion for bow,	<b>270 €</b>
8652070	Safety ladder, telescopic,	<b>313 €</b>
4551639	Extra seatbox	<b>440 €</b>
8517099	Cushion for extra seatbox	<b>317 €</b>
4517081	Flip seats front,	<b>863 €</b>
8517087	Cushions for flip seats, set of 2 pc.,	<b>430 €</b>

### PIONER Trio

5 951 €

4537090	Handrails	<b>607 €</b>
4514070	Safety ladder	<b>165 €</b>

Cennik obowiązuje od 01.04.2023r. Podane ceny nie zawierają podatku VAT oraz transportu. Zastrzegamy sobie prawo do zmiany cennika oraz błędów typograficznych.

**Notice! Extra equipmnet that is included in Special Edition**

Price list valid from August 1st, 2023. Prices in above list are in Euro excl. VAT EXW. Czosnów, Poland. We reserve the right to price changes and typographical errors in the price list.

Address Parker Poland Sp. z o.o., ul. Firmowa 30, 05-152 Czastków Polski, Gmina Czosnów  
Web [www.parker.com.pl](http://www.parker.com.pl)  
NIP: 526-021-13-92 KRS:0000109461 Kapitał zakładowy: 6 000 000,00PLN